

Rm
JWS
3MP

July 6, 1978

Memo to File:

Re: Interstate Brick Company
Jim Gay Mine
ACT/049/005

On June 14th 1978, Brian Buck inspected this open pit clay mine just west of Utah Lake. The only present activity is occasional loading of the stockpiled ore. Since the last inspection, no further failure of the west pit wall has occurred but a progressive slump has developed on the east pit wall. It seems that because of the drastic oversteepened pit walls, further failures are likely which would make future mining here rather hazardous if not impossibly so.

Brian W. Buck *BWB*
Engineering Geologist ~~_____~~

/tlb